

# HH1 Radon Results

RST 3 Sample ID	Serial Number	Building Name	Floor	Room Name	Placement Location	Start Date	Start Time	Stop Date	Stop Time	Comments (Place/PU)	Tech. Place	Tech. Pick- up	Lab Results (pCi/L)
C002- AA001-01	2430436	HH & P Office Trailer	Ground	Office	2' East, 3' North from SW corner on top of a file cabinet	8/4/15	9:40	8/7/15	10:16		AA	AA	0.2
C002- AA002-01	2430444	HH & P Office Trailer	Ground	Reception area	6.2' West, 2.5' North from SE corner on PEI stand	8/4/15	9:44	8/7/15	10:18		AA	AA	0.2
C002- AA002-02	2430432	HH & P Office Trailer	Ground	Reception area	6.8' West, 2.5' North from SE corner on PEI stand	8/4/15	9:45	8/7/15	10:18	Co-located (Duplicate)	AA	AA	0.1
C002- AA003-01	2430423	HH & P Office Trailer	Ground	Lounge	2.3' West, 10' North from SE corner on top of a refrigerator	8/4/15	9:50	8/7/15	10:20	A/C unit was turned on / AC unit off	AA	AA	0.2
C002- AA004-01	2430411	HH & P Storage Trailer	Ground	Storage trailer	8' South from NW corner on a shelf	8/4/15	10:10	8/7/15	10:23	Door was opened / Door still opened	AA	AA	0.3
C002- AA005-01	2431993	HH & P Storage Trailer	Ground	Storage trailer	33' South from NW corner on a table	8/4/15	10:13	8/7/15	10:24	Door was opened / Door still opened	AA	AA	0.2
	2430408	Precision Environmental office	2nd floor	Andrea's office	On top of a file cabinet					Office Blank	AA	AA	0.1